Operator: PEOPLES GAS LIGHT AND COKE CO.	Operator ID#: 15329	
Inspection Date(s): 7/10/2014, 7/7/2014, 7/8/2014, 7/9/2014 Man Days		
Inspection Unit: South Shop	·	
Location of Audit: Chicago		
Exit Meeting Contact: Lance Rainge		
Inspection Type: Standard Inspection - Field Audit		
Pipeline Safety Representative(s): Aaron McElravy		
Company Representative to Receive Report: Tom Webb		
Company Representative's Email Address: TJWebb@peoplesgasdelivery.com		

Headquarters Address Information:	200 E. Randolph Street	
	Chicago, IL 60601	
	Emergency Phone#:	
	Fax#:	
Official or Mayor's Name:	Jodi Caro	Willard Evans
	Phone#: (000) 000-0000	Phone#: (000) 000-0000
	Email:	Email:
Inspection Contact(s)	Title	Phone No.
Eddie Morrow	Senior Engineer	
Lance Rainge	General Manager - South District	(773) 672-6390

	CUSTOMER METER & REGULATOR	Status
Category Comment:		
Staff conducted a previou	us Field audit, inspection # 2014-P-00069 which included this section and requirements.	
[192.353(a)]	Is the customer meter and regulator installed in a readily accessible location and protected from corrosion and other damage, including if installed outside a building, vehicular damage that may be anticipated?	Not Checked
[192.355(b)(1)]	Is the customer regulator vent rain and insect resistant?	Not Checked
[192.355(b)(2)]	Is the customer regulator vent located where gas from the vent escapes freely into the atmosphere and away from building openings?	Not Checked
[192.355(b)(3)]	Is the vent protected from damage caused by submergence in areas of flooding?	Not Checked
[192.357(a)]	Is the customer meter and regulator installed to minimize anticipated stresses	Not Checked

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

	upon connecting piping?	
[192.357(d)]	Is a customer regulator that might release gas vented to the outside atmosphere?	Not Checked
[192.359(a)]	Is the meter operating pressure within the allowable limits of the meter case rating?	Not Checked
[192.365(a)]	Is the service line valve upstream of the regulator or meter?	Not Checked
[192.365(c)]	Is the underground service line valve located in a curb box or standpipe that allows for ready operation?	Not Checked
[192.727(d)][192.727(d)]	When service to the customer has been discontinued has the proper method been utilized to prevent unauthorized usage?	Not Checked
	CATHODIC PROTECTION	Status
Category Comment:		
Staff conducted a previous Fie	ld audit, inspection # 2014-P-00069 which included this section and requirements.	
[192.463(a)]	Is the applicable cathodic protection criteria contained in Appendix D of this part being followed?	Not Checked
[192.465(a)]	Were pipe to soil readings taken?	Not Checked
[192.465(b)]	Were rectifier installations inspected?	Not Checked
[192.465(a)]	Were isolated mains/services tested?	Not Checked
[192.465(c)]	Were critical/non critical bonds tested?	Not Checked
[192.467(a)]	Is electrical isolation provided by use of insulated meter spud, valve, union, or flange?	Not Checked
[192.467(c)]	Were casings installations tested for electrical isolation?	Not Checked
[192.479(a)]	Is the above ground piping coated or painted as required?	Not Checked
[192.479(c)]	Is the pipeline free of corrosion or pitting?	Not Checked
	DAMAGE PREVENTION	Status
[192.614]	Does the operator have a valid notification of planned excavation activities?	Satisfactory
General Comment:		
Staff observed locating of facili	ties at the intersection of Racine and 82nd Street. Ticket # 469013406.	
[265.40(a)]	Did the operator complete the locating activities in the specified timeframe?	Satisfactory
General Comment:		
Staff observed locating of facili	ties at the intersection of Racine and 82nd Street. Ticket # 469013406.	
[192.614(c)(5)]	Were temporary markings made in accordance with the operator's Operation and Maintenance Manual?	Satisfactory

PEOPLES GAS LIGHT AND COKE CO./7-10-2014

Page 2 of 6

General Comment:		
Staff observed locating o	f facilities at the intersection of Racine and 82nd Street. Ticket # 469013406.	
[192.707(a)(1)]	Are line markers placed and maintained as close as practical over each buried main and transmission line located at each crossing of a public road and railroad?	Not Checked
General Comment:		
Staff did not identify line i	markers during this audit.	
[192.707(a)(2)]	Are line markers placed and maintained as close as practical over each buried main and transmission line located wherever necessary to identify the location of the transmission line or main to reduce the possibility of damage or interference?	Not Checked
General Comment:		
Staff did not identify line	markers during this audit.	
[192.707(c)]	Are line markers placed and maintained as close as practical over each main and transmission line located above ground?	Not Checked
General Comment:		
Staff did not identify line i	markers during this audit.	
[192.707(d)(1)]	Do the operator's line markers contain the following information: The following must be written legibly on a background of sharply contrasting color on each line marker: The word "Warning," "Caution," or "Danger" followed by the words "Gas (or name of gas transported) Pipeline" all of which, except for markers in heavily developed urban areas, must be in letters at least 1 inch (25 millimeters) high with ¼ inch (6.4 millimeters) stroke?	Not Checked
General Comment:		
Staff did not identify line	markers during this audit.	
[192.707(d)(2)]	Do the operator's line markers contain the following information: The following must be written legibly on a background of sharply contrasting color on each line marker: The name and phone number (including area code) of the operator where the operator can be reached at all times?	Not Checked
General Comment:	·	
Staff did not identify line	markers during this audit.	
PRESSI	JRE LIMITING AND REGULATING DEVICES (MECHANICAL)	Status
Category Comment:	<u> </u>	
Staff inspected pressure	limiting and regulating equipment at the following locations.	
Vault # 207 Intersection of Vault # 140 Intersection of	of 122nd & May Street of 125th & Michigan Street	

[192.739(a)(4)]	Was each pressure limiting station, relief device (except rupture discs), and pressure regulating station and its equipment subjected at intervals not exceeding 15 months, but at least once each calendar year, to inspections and tests to determine that it is properly installed and protected from dirt, liquids, or other conditions that might prevent proper operation.?	Satisfactory
[192.317(b)]	Is each above ground transmission line or main protected from accidental damage by vehicular traffic or other similar causes?	Not Applicable
General Comment:	<u> </u>	
Staff did not observe above gr	ound facilities.	
[192.741(a),192.741(c)]	Were telemetering and/or recording gauges inspected for abnormally high or low pressure indications?	Satisfactory
[192.743(a)]	Is overpressure protection provided on the pipeline down stream of the take point?	Satisfactory
[192.199(d)]	Were the pressure relief or pressure limiting devices inspected to determine if the support was made of noncombustible material?	Satisfactory
[192.199(e)]	Were the pressure relief or pressure limiting devices inspected to determine if the discharge stacks, vents, or outlet ports were designed to prevent accumulation of water, ice, or snow, and located where gas can be discharged into the atmosphere without undue hazard?	Satisfactory
[192.199(h)]	Was each valve, designed to isolate the system under protection from its source of pressure, secured to prevent unauthorized operation of any stop valve that will make the pressure relief valve or pressure limiting device inoperative?	Satisfactory
	VALVE MAINTENANCE	Status
Category Comment: Staff conducted a previous Fie	old audit, inspection # 2014-P-00069 which included this section and requirements.	
[192.747(a)]	Were the valves inspected accessible?	Not Checked
	ODORIZATION OF GAS	Status
Category Comment: Staff conducted a previous Fie	eld audit, inspection #2014-P-00069 which included this section and requirements.	
[192.625(a)]	Was the odor intensity level readily detectable at or below 1/5th LEL?	Not Checked
[192.625(e)]	Was the Odorization equipment and tank levels inspected?	Not Checked
[192.625(f)]	Was the operator's equipment calibrated as required?	Not Checked
TRANSMISSION		Status
Category Comment: Staff did not inspect transmiss.	ion valves during this audit.	
[192.179(b)(1)]	Are transmission valves protected from tampering or damage?	Not Checked

[192.745(a)]	Were the valves inspected accessible?	Not Checked
[192.719(a)]	Is pre-tested transmission pipe inventory maintained for use in an emergency?	Not Checked
MARKING OF MATERIAL		Status
[192.63(a)]	Does the operator's components and pipe contain the required markings?	Satisfactory
General Comment:		
Staff inspected material during a routine service installation reconnect at 11841 S. Indiana		
OPERATOR QUALIFICATION		Status
Was a PHMSA Form	5 Operator Qualification Field Inspection Protocol Form completed?	No